

FIG.18

| | T1 | T2 | T3 | T4 |
|----|-------|-------|-------|----|
| M1 | 0 | 127.5 | 127.5 | 0 |
| M2 | 127.5 | 127.5 | 127.5 | 0 |
| M3 | 0 | 127.5 | 0 | 0 |

FIG.19

| | |
|----|-------|
| S1 | 255 |
| S2 | 382.5 |
| S3 | 127.5 |

FIG.20

| | T1 | T2 | T3 | T4 |
|----|----|----|----|----|
| M1 | -1 | 1 | 1 | -1 |
| M2 | -1 | 1 | -1 | -1 |

FIG.21

| | |
|----|----|
| S1 | 0 |
| S2 | -2 |